


KEY

M 348	Lamp columns which should have motif attached (as per structural test Oct 2017)
Wr 350	Column shaft to be wrapped in cluster lights even if Str or Corr - confirmed with Structural Engineer
Corr 299	Over 50% corrosion - NEEDS REPLACING. DO NOT ATTACH MOTIF
Str 346	Strength insufficient - NEEDS REPLACING. DO NOT ATTACH MOTIF
DNU Str 349	Strength insufficient - Highway signage too heavy - DO NOT WRAP OR ATTACH MOTIF
	Icicle lights fixed to building frontages

St Albans Christmas Lights locations - November 2017